

# **Experian AutoCheck Report**

Report run: 12/11/2025 13:45:57 EST

### 2006 Honda Accord LX Sedan 4D (2.4L I4 FI Gasoline) 1HGCM564X6A055052 VIN: Class: Car - Midsize

Country of Assembly: **United States** 

Vehicle Age: 19 year(s)

**Last Reported Odometer:** 95,737 (11/10/2025)



Vehicle Usage Fleet

## Vehicle History at a Glance



**State Title Brand** 





**Auction Brand / Issues** 



**NO ISSUE** 



**Accident / Damage** 

No Accidents or Damage Reported



**NO ISSUE** 



**Open Recall Check** 



**NO OPEN RECALLS** 



**Insurance Loss / Transfer** 



**NO ISSUE** 



**Odometer Check** 

Last reported odometer: **95,737 (11/10/2025)** 



**NO ISSUE** 



**Certified Pre-Owned** 



**NO CPO INFO AVAILABLE** 



Service / Repair

5 Service Record(s) Reported



**NO ISSUE** 



**Additional History** 

Lien Reported



**EVENTS REPORTED** 



### This vehicle is AutoCheck Assured™


This vehicle does not have any state title brands or other major problems reported.

Learn More



📇 Accident & Damage

**Your Vehicle Checks Out** There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



# Odometer Check



#### **Your Vehicle Checks Out**

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



#### **State Title Odometer Check**

No issues reported



### **Auction Odometer Check**

No issues reported



### **Odometer Calculation Check**

No issues reported

# Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order. Vehicle: 2006 Honda Accord LX (1HGCM564X6A055052) Report Run Date: 12/11/2025 13:45:57 EST

### 2005

## **Vehicle Prep and Other Pre-Titling Events**

Location: CA	Preparation Date:	12/2005		
Event Date	Location	Odometer	Data Source	Details
12/31/2005	CA	10	Motor Vehicle Dept.	Odometer Reading from DMV

# 2006

## Owner 1

Location: CA		Owned From: 01/2006	Usage: Fleet	
Event Date	Location	Odometer	Data Source	Details
01/25/2006	IRVINE, CA		Motor Vehicle Dept.	Registration Event/Renewal
01/27/2006	IRVINE, CA		Motor Vehicle Dept.	Title(Lien Reported)
08/09/2007	IRVINE, CA		Motor Vehicle Dept.	Title(Lien Reported)
08/09/2007	IRVINE, CA		Motor Vehicle Dept.	Registration Event/Renewal
01/02/2008	IRVINE, CA		Motor Vehicle Dept.	Registration Event/Renewal
08/19/2010	IRVINE, CA		Motor Vehicle Dept.	Registration Event/Renewal
09/01/2010	IRVINE, CA		Motor Vehicle Dept.	Title

	Event Date	Location	Odometer	Data Source	Details
	06/12/2012	IRVINE, CA		Motor Vehicle Dept.	Registration Event/Renewal
Ely NE, CA   2,114   Sarv de Record   Sarvey Services of Replaced Subtract of Profit Validation Impactation Impa	12/17/2012	CA	52,381	State Agency	Passed Emission Inspection
Multiple Port Vende Impession   Signa Season   Signa Season   Signa Se	12/16/2016	CA	68,376	Motor Vehicle Dept.	Passed Emission Inspection
Print   CA   Print   CA   Print   CA   Print   CA   Print   Changed   A Filter Changed	11/21/2017	IRVINE, CA	72,114	Service Record	Multiple Point Vehicle Inspection Engine Serviced Wipers Replaced And/Or Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
Air File Changed Battery Serviced Preplaced Multiple Point Vehicle Inspection Engine Serviced Batters Serviced Preplaced Service Performed Lute. CJ Ard Mor File Changed Vehicle Files Serviced Proposed Service Performed Lute. CJ Ard Mor Files Changed Vehicle Files Serviced Preplaced Service Performed Lute. CJ Ard Mor Files Changed Vehicle Files Serviced Preplaced Multiple Point Vehicle Inspection Engine Serviced Suspension Performed Lute. CJ Ard Mor Files Changed Vehicle Files Serviced Preplaced Multiple Point Vehicle Inspection Engine Serviced Serviced Preplaced Performed Lute. CJ Ard Mor Files Changed Vehicle Files Serviced Preplaced Performed Lute. CJ Ard Mor Files Changed Serviced Preplaced Performed Lute. CJ Ard Mor Files Serviced Preplaced Multiple Point Vehicle Inspection Engine Serviced Files Serviced Preplaced Multiple Point Vehicle Inspection Engine Serviced Files Serviced Preplaced Performed Lute. CJ Ard Mor Files Changed Service Performed Lute. CJ Ard Mor Files Changed Performed Lute. CJ Ard M	12/28/2018	CA	76,505	Motor Vehicle Dept.	Passed Emission Inspection
12/21/2020         CA         83.687         Motor Vehicle Dept.         Passed Emission Inspection Engine Serviced Denny Parish Inspection Engine Serviced Tires or Wheels Serviced           10/01/2021         CA         83.687         Motor Vehicle Dept.         Passed Emission Inspection           10/01/2021         RMINE CA         85.361         Service Record         Fuel System Serviced and Englaced Multiple Point Vehicle Inspection Englaced Englac	01/14/2019	IRVINE, CA	76,722	Service Record	Air Filter Changed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Drive Line Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
IRVINE, CA  REVINE, CA  REVINE, CA  REVINE, CA  REVINE RECORD  REVINES Serviced or Replaced Air Filter Changed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced  Revines Serviced Brakes Serviced Brakes Serviced Brakes Serviced Revised Revised Brakes Serviced Performed Lube, Oil And/OF Filter Changed Vehicle Fluids Serviced Performed Lube, Oil And/OF Filter Changed Vehicle Fluids Serviced Revised Fluids Serviced Revised Fluids Serviced Cooling System Serviced Cooling System Serviced Fluids Serviced Revised Fluids Serviced Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Fluids Serviced Recommended Mintenance Performed Transmission Serviced Fluids Serviced Recommended Mintenance Performed Transmission Serviced Fluids Serviced Fluids Serviced Fluids Serviced Recommended Mintenance Performed Transmission Serviced Fluids Serviced Fluids Serviced Fluids Serviced Recommended Mintenance Performed Transmission Serviced Fluids Serviced Fluids Serviced Fluids Serviced Fluids Serviced Fluids Serviced Recommended Mintenance Performed Transmission Serviced Fluids Flu	03/09/2020	IRVINE, CA	81,329	Service Record	Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Suspension Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
12/14/2022CA87,147Motor Vehicle Dept.Passed Emission Inspection Engine Serviced Transmissions Vehicle Fluids Serviced Orally Point Vehicle Inspection Engine Serviced Brakes Serviced Transmissions Serviced Brakes Serviced Prince of Wheels Serviced Vehicle Fluids Serviced12/14/2022CA87,147Motor Vehicle Dept.Passed Emission Inspection10/18/2023Brakes Serviced Arrighter Changed Multiple Point Vehicle Inspection Engine Serviced Pull System Serviced Arrighter Changed Multiple Point Vehicle Inspection Engine Serviced Princed Princed Princed Princed Princed Princed Princed Princed Princed Princed Princed Princed Princed Princed Princed Princed Princed Princ	12/21/2020	CA	83,687	Motor Vehicle Dept.	Passed Emission Inspection
10/18/2023  IRVINE, CA  89,499  Service Record  Steering System Serviced Cooling System Serviced Cooling System Serviced Fuel System Serviced Recommended Maintenance Performed Transmission Serviced Recommended Maintenance Performed Transmission Serviced Electrical System Serviced Electrical System Serviced Electrical System Serviced Fuel System Serviced Recommended Maintenance Performed Transmission Serviced Electrical System Serviced Electrical	10/01/2021	IRVINE, CA	85,361	Service Record	Air Filter Changed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Transmission Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
Cooling System Serviced Fuel System Serviced Fuel System Serviced Fuel System Serviced Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Transmission Serviced Brakes Serviced Electrical System Serviced Electrical System Serviced Tires or Wheels Service Performed  12/18/2024 CA 94,590 Motor Vehicle Dept. Passed Emission Inspection  10/29/2025 HELENA, MT Title(Lien Reported) Excluded/Exempt  10/30/2025 PACIFIC SW REGION 95,737 Auto Auction Reported at Auto Auction  11/03/2025 CA 95,737 Auto Auction Auction Announced as Fleet/Lease	12/14/2022	CA	87,147	Motor Vehicle Dept.	Passed Emission Inspection
10/29/2025 HELENA, MT Motor Vehicle Dept. Title(Lien Reported) Excluded/Exempt  10/30/2025 PACIFIC SW REGION 95,737 Auto Auction Reported at Auto Auction  11/03/2025 CA 95,737 Auto Auction Auction Announced as Fleet/Lease	10/18/2023	IRVINE, CA	89,499	Service Record	Cooling System Serviced Fuel System Serviced Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Transmission Serviced Brakes Serviced Electrical System Serviced
Excluded/Exempt 10/30/2025 PACIFIC SW REGION 95,737 Auto Auction Reported at Auto Auction 11/03/2025 CA 95,737 Auto Auction Auction Auction Announced as Fleet/Lease	12/18/2024	CA	94,590	Motor Vehicle Dept.	Passed Emission Inspection
11/03/2025 CA 95,737 Auto Auction Auction Announced as Fleet/Lease	10/29/2025	HELENA, MT		Motor Vehicle Dept.	
	10/30/2025	PACIFIC SW REGION	95,737	Auto Auction	Reported at Auto Auction
11/10/2025 UPLAND, CA 95,737 Dealer Listing Vehicle in Dealer Inventory	11/03/2025	CA	95,737	Auto Auction	Auction Announced as Fleet/Lease
	11/10/2025	UPLAND, CA	95,737	Dealer Listing	Vehicle in Dealer Inventory

### **AutoCheck Terms and Conditions**

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

### **About AutoCheck**

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

#### **Patent Notice**

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.